

**PIERCE COUNTY**

<b>SITE ID:</b>	<b>SSA Containers Inc</b>	Cleanup Site ID: 3438	FS ID: 68593938
	Alternate Name(s):		

<b>LOCATION:</b>	WRIA: 10	Lat/Long: 47.268 -122.388	<a href="#">View Vicinity Map</a>
<b>Address:</b>	3320 LINCOLN AVE E TACOMA 98421	Township 21N Range 3E Section 35	Legislative District: 27 Congressional District: 9

<b>STATUS:</b>	<b>Cleanup Started</b>	Rank:	<a href="#">View Site Web Page</a>	<a href="#">View Site Documents</a>
	Responsible Unit: Southwest	Site Manager: Leja, Stan	Statute: MTCA	
	Is Brownfield?	Has Environmental Covenant?	Is PSI Site? Yes	
	NFA Received?	NFA Date:	NFA Reason:	

**ASSOCIATED CLEANUP UNIT(s)**

culD	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
4222	REICHHOLD CHEMICALS INC	Upland	Ecology-supervised or conducted	Cleanup Started		

**SITE ACTIVITIES:**

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite MilestoneType		Ecology Cleanup Construction	Completed	5/12/2007	9/29/2010	Agreed Order	Ecology	Leja, Stan

**AFFECTED MEDIA & CONTAMINANTS:**
**Media:**

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Phenolic Compounds	C		C			
Polychlorinated biPhenyls (PCB)	C		C			

**Key:**

B - Below Cleanup Level  
C - Confirmed Above Cleanup Level  
S - Suspected

R - Remediated  
RA - Remediated-Above  
RB - Remediated-Below

CleanupSiteDetails2014